Customer

Job Number

P.O. Number

This Issue

Prsht Rev.

First Issue

Written By

Previous Run

Estimate Number

Friday, 5/25/2007 8:36:53 AM Kim Johnston

: 32648 - 1

: 12884

: NA

: NIA

: 5/25/2007

Process Sheet

Drawing Name

POSITIVE RECALL

EFFECTIVE U7.06.05 AUTH

ELEASED 17.46 66 DATE

: D3560044 Part Number

: ARM

D3560 REV.B **Drawing Number** : N/A

Project Number **Drawing Revision** : NIA

Material : 6/5/2007 Due Date

Each

Checked & Approved By Comment

: Est Rev:A

: CU-DAR001 Dart Helicopters Services

Type

New Issue 07.05.24

: SMALL /MED FAB

Additional Product

Job Number:



Machine Or Operation: Seq. #: M6061T6B0500X05000 1.0

Description:

6061-T6 Bar .50" x 5.0"

Comment: Qty.: 1.3598 f(s)/Unit

Total: 40.7925 f(s)

6061-T6 Bar 0.50" x 5.00"

M104598 x20 Batch: 17675

36

20

EC



Comment: BAND SAW

Cut blanks 15.500" long

3.0

HAAS1

HAAS CNC VERTICAL MACHINING #1

Comment: HAAS CNC VERTICAL MACHINING #1

1- Mill as per Folio FA696 Rev: 44 & Dwg D3560 Rev: 3

2-C'sink 0.196" hole on manual mill as per dwg D3560

3-Deburt per dwg D3560

20

40

QC2

INSPECT PARTS AS THEY COME OFF MACHINE

Comment: INSPECT PARTS AS THEY COME OFF MACHINE

26

5.0

QC8

SECOND CHECK

Comment: SECOND CHECK



Dart Aerospace Ltd

Dant Ae	Tospace	WORK ORDER CHAN	IGES				
W/O:	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
07.Us.Us	1(NO POWDER COAT. CHEM CONV. COAT ONLY. REF ATTACHED IN GMAIL	701			451047	POROS-11
71×(20	3 \$4	D 2808 Betch B32752 Put Bushing	12	01.06.27	6	07.08.16	


Part No:	PAR #:	Fault Category:	NCF	R: Yes No DQA:	Date: 67/0+104
raicito.			2	QA: N/C Closed:	Date:

NCR:		VV	JKK OKI	DER NON-CONFORMANCE	_ (,			**
DATE STEP		Description of NC	Corrective Action Section B			Verification	Approval Chief Eng	Approval QC Inspector
		Section A	Chief Eng	Initial Action Description Chief Eng		SectionC	Ciller Elig	CC IIIsuacioi
		Kinzow Food, bogpoux Food -		scrap + replace	コト	(/	//	(/
4/0/10	5	clamp tight enough causing blank to the move while	Posicie	,desloy	orladio	PC70611	Pasion	07-06-11
7/001.		machining on 1st one	1	Remove the 03/592-1 plate and	/		1	1
		04/6 pm to have cracked on the 03592-1 plate, che to too much	1	grand Any access well flush	07.0823	a.m	-7	//
70822	8.0	heat transfer to gain deeper penetration during walding.	031042	Went And by Q.C.	15	1	QYOUR	107062
		R.C: Too hot of a well on the	6,	dell plate of per Duy	01 0 01	Aldoi		
	1	PIZZE. NUMITHI ENVOY		scrippi destroy		V HILT OF		

NOTE: Date & initial all entries



Date: Wednesday, 15/08/2007 7:40:40 AM Linda Lacelle User: **Process Sheet** Drawing Name: ARM Customer: CU-DAR001 Dart Helicopters Services Job Number: 32648 Part Number: D3560044 ob Number: Description: Seq. #: Machine Or Operation: INSPECT PARTS AS THEY COME OFF MACHINE 5.0 QC2 Comment: INSPECT PARTS AS THEY COME OFF MACHINE SECOND CHECK 6.0 Comment: SECOND CHEC D35921 PLATE 7.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 30.0000 Each(s) Comment: LARGE FABRICATION RESOURCE 1 1-Weld assembly as per dwg D3560 9.0 QC5 INSPECT WORK TO CURRENT STEP Comment: INSPEC TO CURRENT STEP QC9 VISUAL WELDING INSPECTION 10.0 Comment: VISUAL WELDING INSPECTION 7-10-0 HAND FINISHING1 HAND FINISHING RESOURCE #1 11.0 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 12.0 POWDER COATING POWDER COATING Comment: POWDER COATING Powder Coat White Gloss (Ref. 4.3.5.1) as per QSI 005 4.3



Cate: User:

Wednesday, 15/08/2007 7:40:40 AM

Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: ARM

Job Number: 32648

Part Number: D3560044

ob Number:



Seq. #:

Machine Or Operation:

Description:

13.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION

Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

14.0

SMALL & MEDIUM FAB RESOURCE 1





Comment: SMALL & MEDIUM FAB RESOURCE 1

15.0

PACKAGING

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock Location:

16.0

QC21

FINAL INSPECTION/W/O RELEASE



17.0

EMP COST ADJ

Employee Labour Cost Adjustment



Comment: Sub-Contracting Employee Labour Cost Adjustment

Job Completion



n 07-10.02




D3560-1 ARM (-041, SHOWN)
OR D3560-2 ARM (-042, OPPOSITE)

D3592-1 PLATE,
SEE DETAIL A

D3560-041 ARM WELDMENT (SHOWN), D3560-042 ARM WELDMENT (OPPOSITE) D3560-3 ARM (-043, SHOWN)
OR D3560-4 ARM (-044, OPPOSITE)

D3592-1 PLATE,
SEE DETAIL A

D3560-043 ARM WELDMENT (SHOWN), D3560-044 ARM WELDMENT (OPPOSITE) Cef 32648





DETAIL A (SCALE 1:1)

GENERAL NOTES

- 1) WELD PER QSI 004
- 2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) ALL DIMENSIONS ARE IN INCHES



	С		07.06.19	REMOVE POWDE	R COAT
	8		07.01.15	REDESIGN AS W	VELDMENT, ADD POCKETS
	A		06.09.25	NEW ISSUE	
COPYRIGHT @ 2006 BY DART AEROSPACE LTD.	DESIGN	90	ORAWN BY	DART	DART AEROSPACE LTD.
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL, AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE	CHECKED	#	APPROVED	DRAWING NO. D3560	REV. C
OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM	DATE			TITLE	SCALE
DART AEROSPACE LTD.	07.06.19			ARM WELDMENT	194



